## METHOD AND DEVICE FOR EXPOSURE CONTROL, METHOD AND DEVICE FOR EXPOSURE, AND METHOD OF MANUFACTURE OF DEVICE

## ABSTRACT

5

10

15

20

A method for exposure control comprising the steps of measuring the change of the transmissivity or transmittance for the light incident to the projection optical system prior to the exposure operation effected by illuminating a pattern on a reticle to form an image of the pattern on a photosensitive wafer through the projection optical system, storing the measured change of the transmissivity, sequentially measuring the amount of the light incident to the projection optical system during the exposure operation, calculating the exposure light amount for the photosensitive wafer from the exposure light amount based on the stored change of the transmissivity, and integrating the exposure from the start of the exposure operation to terminate the exposure operation when the total exposure light amount has reached a predetermined value. The total exposure light amount for the wafer surface can be controlled even if the transmissivity of the projection optical system fluctuates.